

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1170
ENE
> 1
1.546 mi.
8163 ft.

PETCO PARKING LOT
EAST 17TH STREET & AVE Y
BROOKLYN, NY

NY Spills S108763673
N/A

Relative:
Higher

Actual:
19 ft.

SPILLS:

Name: PETCO PARKING LOT
Address: EAST 17TH STREET & AVE Y
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0705502 / 2007-08-17

Facility ID: 0705502
Facility Type: ER
DER Facility ID: 335207
Site ID: 385825
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 2401
Spill Date: 2007-08-12
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2007-08-14
CID: 444
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Not reported
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2007-08-14
Spill Record Last Update: 2007-08-17
Spiller Name: SANDRA BETELAK
Spiller Company: PETCO PARKING LOT
Spiller Address: EAST 17TH STREET & AVE Y
Spiller Company: 001
Contact Name: SANDRA BETELAK
DEC Memo: "Sangesland has left messages for sandra betelak, but no response.
Unknown what the problem is at the site. After several days of no
response from Ms. Betelak - spill closed"

Remarks: "UP AGAINST FENCE THEY ARE STORING HAZARDOUS MATERIALS IN BARRELS AND
SHE SAID A TEST WAS PERFORMED AND SHE WANTS TO KNOW WHAT THE TESTS
RESULTS ARE:"

All Materials:

Site ID: 385825
Operable Unit ID: 1143086
Operable Unit: 01
Material ID: 2133343
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported